

CALVES Keep the knee slightly bent (about 30°) and measure the circumference (cm) around the widest part of the calf.



	S	M	L	XL	XXL	XXXL
7756, 7758, 7760	34–36	36–38	38–41	41–44	44–47	
7760W, 7960	33–35	35–37	37–39	39–41		
7708	34–38		38–43		43–49	